## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 42-43 M.R. 14 W

			Schoole	Schoolcraft	
DESCRIPTION OF CORNER	Section corner	r common to Se	ctions 2, 3, 34	. 35	
CORMER MONUMENT 1" Pipe with 4" Brass Cap					
DATE MONUMENT PLACED	AND WITHESSED	5/9/61			<del> </del>
WITHESSES TO CORNER	12" Tamarack	(S 2 NBT)	S 08° E	38 1/2 <u>Links</u>	
N	10" Cedar	( s 35 NBT)	n 59° e	24 Links	
35	6" Cedar	(S 3 NBT)	s 76° w	15 Links	
CIRCLE CORNER REGISTER	AND			<u>-</u>	

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established by single proportionate measurement between 1/4 corner 1/2 mile west and Section Corner 1 mile East. No original evidence.

SURVEYOR'S SEAL

SIGNED Silly Suckles DATE 9/15/61

REG/STERED LAND SURVEYOR

Bully D. Buckler