

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES  
LAND CORNER RECORD

Schoolcraft COUNTY


T 42 N R's 14 & 15W

DESCRIPTION OF CORNER 1/4 corner for sections T42N R15W 13/18 T42N R14W

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 11/5/69, F. J. Bray with M. Burnis

WITNESSES TO CORNER..... 8" Cedar (1/4 S) (NBT) N 58° W, 09 links



9" Cedar (1/4 S) (NBT) S 07° E, 10 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between section corners to north and to south. Corner checks fairly well with stream crossing.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray  
REGISTERED LAND SURVEYOR  
Frank J. Bray

DATE

11/19/69

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68