

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42. NR. 14, 15 W

Schoolcraft COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 13, 24, 18, 19.

DESCRIPTION OF CORNER MONUMENT 2" iron pipe with 2½" brass cap

WITNESSES TO CORNER

8" Cedar	Marked	S 65° W " S 24 NBT"	12½ links
6" Cedar N	Marked	N 15° W " S 13 NBT"	25 links
7" Cedar	Marked	N 22° E " S 18 NBT"	42 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-witnessed pipe as set by Carl Christianson, Manistique.

One Cedar B.T. in place, good condition.

Shown to us by Carl Makel, D. F.

Corner re-witnessed January 8, 1957.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 1-11-57
REGISTERED LAND SURVEYOR