

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42. NR. 15 W.

Schoolcraft

COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 30, 31

DESCRIPTION OF CORNER MONUMENT 2" iron pipe with 2" brass cap

WITNESSES TO CORNER 6" Cedar N 85° E 24 links
Marked " 1/4 S NBT"

7" Cedar N 27° E 31 links
Marked " 1/4 S NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-witnessed 1/4 Corner, pipe, placed by Carl Christianson, Manistique.

Cedar B.T., still growing in excellent condition.

Shown by Carl Makel, D.F.

Corner re-witnessed January 8, 1957

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 1-11-57
REGISTERED LAND SURVEYOR