LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

SCHOOLCRAFT CO. 2 CORNERS.

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 42 N. R. 16 W.	M-9, M-10
2. PROPERTY CONTROLLING IN SECTION	T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Gerald L. Wiggins, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 9-8, 19 87, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

M-9 Southeast corner of section 24. OBT'S: Spruce 8, N27W, 39 lks. & Tamarack 5, S80°W, 19 lks. & Tamarack 10, S75°E, 1.42 chs.

M-10 East 1/4 corner of section 25. OBT'S: Cedar 8, N66°W, 39 lks. & Fir 9, S74°W, 25 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

M-9 Set corner by single proportionate measure along Township Line from original corners 1 mile North and 1 mile South. Proportionate measure West 1 mile to Section Corner and East 1/2 mile to Slough fit original measure. Distance West to Stream fits original.

M-10 Corner set midpoint on line between N.E. Corner and S.E. Corner of Section 25. 3 river crossings match original measure. Found Cedar stump bottom that fits original bearing & distance Cedar 12, N66°W, 39 lks.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

DNR MOUMENT PLACED AT BOTH CORNERS.

M-9 Sq. Cedar Post, SW, 1.0'
6" D. Tamarack, S35°E, 55.5'
1/4 Corner, North, 2656.72'
1/4 Corner, South, 2656.72'
1/4 Corner, West, 2659.13'

M-10 14" R. Maple, S72°E, 9.9'
8" Cedar, N12°W, 19.3'
22" Cedar, N30°W, 22.7'
6" B. Ash, N85°W, 10.6'

SIGNED BY Gerald L. Wiggins DATE 2-5-88

Gerald L. Wiggins

SURVEYOR'S MICHIGAN REGISTRATION NO. 23521

STATE OF MICHIGAN GERALD L. WIGGINS LAND SURVEYOR No. 23521 (SEAL) REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET