

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

SCHOOLCRAFT

(County)

Located In:

Corner Code *##*

1. Public Land Survey	T <u>42N</u> R <u>17W</u>	K-9
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S <u>36</u> T <u>42N</u> R <u>17W</u>	<u>16</u>
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													

I, Gerald L. Wiggins in a field survey on 12-20- 19 89 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

K-9 N.W. Section Corner of Section 25. DBT'S: 9" Birch, N57°W, 25 lks & 10" Tamarack, S72°W 25 links.

16 East 1/16 Corner on south side of Section 36. Not previously set.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:


K-9 Witnessed found D.N.R. Monument set by Gregory A. Shadko L.S. #01934 in 1940.

16 Found squared concrete monument set by unknown Surveyor.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-9 4" Brass DNR Monument. 16 Sq. Concrete Monument

12" Cedar, S47°W, 7.8'	14" Maple, N55°W, 2.9'
10" Cedar, N78°W, 7.85'	8" Maple, S65°W, 19.6'
8" Cedar, N42°W, 4.2'	6" Maple, S1°E, 18.9'
8" Cedar, N43°E, 31.0'	12" Maple, S74°E, 41.2'



Signed by

Gerald L. Wiggins

23521

Date 3-12-90