

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 14W


Schoolcraft COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ Corner between Sections 28-33

CORNER MONUMENT 4" Concrete Monument with $\frac{1}{2}$ " Pipe in center.

DATE MONUMENT PLACED AND WITNESSED 5-4-61 with D. St. Ours

WITNESSES TO CORNER..... 9" Yellow Birch ($\frac{1}{4}$ S NBT) N5°W 13 $\frac{1}{2}$ links



9" Cedar ($\frac{1}{4}$ S NBT) S23°W 70 links

13" Hemlock ($\frac{1}{4}$ S NBT) S28°E 67 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-witnessed as set by Carl Christiansen, Maristiqua. Both B.T.'s are still green and in fair condition; Y. Birch N52°E 08 links and Hard Maple S65°W 46 links.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE December 28, 1961
REGISTERED LAND SURVEYOR
Billy D. Buckler