

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 43 N.R. 14W


Schoolcraft COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 19-20-29-30

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 5-24-61

WITNESSES TO CORNER..... 7" Jack Pine (S30 NBT) S25°W 85 links



No others available

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established at site of old blazes and in line with old blazes to North. Checks with good Corner  $\frac{1}{2}$  mile East.  
No positive evidence of original corner.

SURVEYOR'S SEAL

SIGNED

*Billy D. Buckler*  
REGISTERED LAND SURVEYOR  
Billy D. Buckler

DATE

December 28, 1961