

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 14W


Schoolcraft COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ Corner on West side Section 18

CORNER MONUMENT 1" Pipe with 4" Brass Cap.

DATE MONUMENT PLACED AND WITNESSED 5-24-61

WITNESSES TO CORNER..... 5" Red Pine ($\frac{1}{2}$ S 18 BT) N10°E 112 $\frac{1}{2}$ links



7" Jack Pine (BT) S76°E 39 $\frac{1}{2}$ links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established 2.04 $\frac{1}{2}$ chains North (record distance) of $\frac{1}{4}$ Corner on East side Section 13, T43N, R15W.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE December 29, 1961
REGISTERED LAND SURVEYOR
Billy D. Buckler