

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43. NR 13 - 14. W

Schoolcraft COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 6, 7, 1, and 12.

DESCRIPTION OF CORNER MONUMENT 4" Concrete Monument with 1/2" iron bolt
in center.

WITNESSES TO CORNER 13" Hard Maple (S 6 NBT) N 43° E 33 1/2 Links

9" Hemlock (S 1 NBT) N 25° W 40 Links

10" Hard Maple (S 7 NBT) N 37° E 48 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED. This corner was re-witnessed as set by unknown surveyor. Maple
B. T. bearing S 60° W 1 Link. Still in place (poor condition). Corner
lies in N. - S. fence line. Found by Forestry Division Survey Crew.

Corner was placed and witnessed February 26, 1958.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 2/24/60
REGISTERED LAND SURVEYOR
Billy D. Buckler