

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43. NR. 14. W

Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 20 and 29

DESCRIPTION OF CORNER MONUMENT 4" Iron Pipe filled with concrete

WITNESSES TO CORNER 6" Jack Pine (1/4s NBT) N 40° W 24 Links

5" Jack Pine (1/4s NBT) S 56° W 31 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

RESTORED. This corner was re-witnessed as set by unknown surveyor, Jack Pine B. T. bearing N 18° E 10 Links, in good condition. 1/4 corner lies on top of ridge. Found by Forestry Division, Survey Crew.

Corner was placed and witnessed March 11, 1958.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 2/24/60