

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 43 N.R. 14 W


Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 23 and 24

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 8/15/61

WITNESSES TO CORNER....2" Jack Pine (1/4 S) S 70° W 17 1/2 Links



5" Jack Pine (1/4S NBT) N 05° W 05 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between section corners.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 9/15/61  
REGISTERED LAND SURVEYOR  
Billy D. Buckler