

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 43 N.R. 14 W


Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 28 and 29

CORNER MONUMENT 1" Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 5/4/61 with D. St. Ours

WITNESSES TO CORNER... 5" J. Pine (1/4S NBT) S 38 deg. E 17 Links



4" J. Pine (1/4S NBT) N 81 deg. W 37 Links

5" B. Spruce (1/4S NBT) N 11 deg. E 22 1/2 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established midway and on line between two Section Corners. No evidence of original corner. Placed location poster 4.00 chains North on Road.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 9/15/61  
REGISTERED LAND SURVEYOR  
Billy D. Buckler