

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 15 W


Schoelcraft COUNTY

DESCRIPTION OF CORNER 1/4 corner for sections 20-21

CORNER MONUMENT 1" Pipe with 4 ♣ Brass Cap

DATE MONUMENT PLACED AND WITNESSED 1/25/61 with Art Enger.

WITNESSES TO CORNER...8" Cedar (1/4th NBT) N 38° E 46 Links



6" Tamarack (1/4th NBT) S 72° E 47 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from one Cedar B.T. in poor condition bearing N 49° E 17 Links. Found overgrowth in scribe marks. Corner found by Art Enger, Assistant District Forester. Corner lies 30 links east of stream.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 2/22/61
REGISTERED LAND SURVEYOR
Billy D. Buckler