


MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION



# LAND CORNER RECORD

T. 44/43 N. R. 15 W


Schoolcraft COUNTY

DESCRIPTION OF CORNER Section corner for sections 33/34 T44N R15W  
4/3 T43N R15W

CORNER MONUMENT 1" Iron pipe with 4" Aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8/3/67, Frank J. Bray with M. Burnis

WITNESSES TO CORNER..... 27" W. Pine (S34NBT) N 51° E, 41 Links



18" W. Pine (S3)(NBT) S 30° E, 77½ Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Placed on line and the single proportioned measurement between section corner to east and 1/4 corner to west. No original evidence found.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 10/16/67  
Frank J. Bray  
REGISTERED LAND SURVEYOR