STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

	_SchoolcraftCOUNTY
	T <u>43N</u> R <u>15 W</u>
DESCRIPTION OF CORNER _	$1/4$ corner for sections $\frac{21}{28}$
CORNER MONUMENT	l" iron pipe with 4" aluminum cap
DATE MONUMENT PLACED AND WITNESSED 8/1/69 F. J. Bray and M. Burnis	
WITNESSES TO CORNER	5" cedar (1/4S) (NBT) N 32° W, 11 links
2 8	7" Cedar (1/4S) (NBT) N 61° E, 16% links
	AND
CIRCLE CORNER REGISTERED	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed on line and midway between section corners to east and to west.

SURVEYOR'S SEAL

DISTRIBUTION:

GNED Treath Sea

DATE 0/1/0

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing