STATE OF MICHIGAN DEPARTMENT 0F NATURAL RESOURCES

LAND CORNER RECORD

ئـــ ئــــ	SCHOOLCRAFT	COUNTY
T	_43 N	R <u>15 w</u>
DESCRIPTION OF CORNER 1/4 corner for Sections 10		
CORNER MONUMENT 1" iron pipe with 4" aluminum cap		
DATE MONUMENT PLACED AND WITNESSED 4/6/72 F. J. Bray wi		
WITNESSES TO CORNER 24" W. Pine (38 NBT) S30°W, 51.	th M. Burnis	
N 11118 (25 NBI) S30W, 51.9	91	
16" W. Pine (% NBT) N38°W 120.5	51	
10		
AND		
V (
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between the section corners to the east and to the west. No original evidence was found.

SURVEYOR'S SEAL

DISTRIBUTION:

REGISTERED LAND SURVEYOR

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing