LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T. 43 N. R. 15 W.	8	
2. PROPERTY CONTROLL- ING IN SECTION—	23 ,T. 43 \$; R. 15 ¥.	10	
	,T		
4. LOT NO , RE	CORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in a field survey on restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law: A. Description of original monument and accessories and/or subsequent restoration: Woodport: 1-8 Sugar 8 870 2 16 links			
B. Description of corner evi	idence found and/or method ap	plied in restoring or re-estab	olishing corner:
I-8 This corner	was placed midway and ad to the south.		
10 This corner	vas placed midway and h and % corner to the s		section corner
All 1" iron p	ipe with 4" aluminum co	. All bearings are	ating the position of the corner:
I-8 18" W. Pin 6" B. Che	e (%) (NBT) N86°E Fry (%) (NBT) N22°E	25.8' 15.4'	
10 9" W. Pine 9" R. Pine	(8 1/ 16) (BT) B61 W (8 1/ 16) (BT) 873 E	15.9' 49.8'	
SIGNED BY		DATE	
SURVEYOR'S MICHIGAN R	LEGISTRATION NO		(SEAL)
FOR STATE AND UNITED	STATES AGENCIES:		
SIGNED BY			
APPROVED AND SIGNED I	MICHIGAN REGISTERED LA	DATE -	1/9/53 (SEAL)
SURVEYOR'S MICHIGAN R	EGISTRATION NO. 1357	75	