

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 16 W


Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sec. 26 and 27.

CORNER MONUMENT 2" L.D. iron pipe with 2 1/2 brass cap stamped "27- 1/4 - 26. c.c "

DATE MONUMENT PLACED AND WITNESSED Placed in 1949; rewritten 3/3/64.

WITNESSES TO CORNER..... Cedar 5 579W 18 1/2 links. "1/4 s. NBT"



do 7 s18e 35 1/2 links. "1/4 s. NBT"

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner located and pipe set by Carl Christensen and Carl Makel from one original bearing tree stump, Cedar 10 N65E 21 links. Stump of BT present in 1964, but only old axe marks are visible.

SURVEYOR'S SEAL

SIGNED Arthur O. Enger RLS 13581

DATE _____

REGISTERED LAND SURVEYOR
Billy D. Buckler RLS 8887

4/13/72

Billy D. Buckler