

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 16 W


Scheelcraft COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 11, 12, 13, 14

CORNER MONUMENT 1" Pipe with 1/2" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 1/25/61 with Art Enger,

WITNESSES TO CORNER... 6" Tamarack (S 11 NBT) N 15° W 73 Links



6" Cedar (S 11 NBT) N 86° W 55 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from one Tamarack B.T. in good condition bearing S 75° E, 24 Links. Tamarack is a shattered stub. Corner lies in open Spruce March. Found by Art Enger, Assistant District Forester.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 2/22/61

Billy D. Buckler