LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Schoolcraft Co.

2 Corners.

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	-
1. PUBLIC LAND SURVEY	T. 44 N. R. 13 W.	E -10	
2. PROPERTY CONTROLL- 28	,T. 44 N. R. 13 W.	8	
3. MISCELLANEOUS PROPERTY IN SECTION	,T		
4. LOT NO , RECORDED PLAT			
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER

I. David B. Babbitt do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 4-20, 1983, established. re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on ______, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

- A. Description of original monument and accessories and/or subsequent restoration:
- E-10 West 1/4 corner of section 28. Wood Post, OBTS Beech 9", 578°W, 28 lks. & 'Sugar 8", N63°E, 08 lks.
- West 1/16 corner of section 28. Not prev. set. 8
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- E-10 Corner set M.P.O.L. between NW section corner and SW section corner of section 28.
- Corner set M.P.O.L. between West 1/4 corner and center corner of section 28. 8

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

DNR monunment set at both corners. Bearings:

(BEAL)