Coms. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 44 M.R. 15-16 W.

	Schoolcraft	COUNTY
DESCRIPTION OF CORNER Section Corner 18, 19, 13, 24		
CORNER MONIMENT 2" I.D. iron pipe with 2 1/2" bras	s cap stamped #13, 24, 18	19, c.c"
DATE MONUMENT PLACED AND WITHESSED Placed in 1949; res	witnessed 8/30/63	
WITHESSES TO CORNER White Pine 16 N73E 28 1/2	links, "S18, NRT"	
do 16 N35W 65	* "S13, NRT"	
44= 15 Red Maple 8 S 63 1/2E 36	8 9 11519 NBTH	
CIRCLE COMER REGISTERED	₩ ₩S24 NBТ#	

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner located and pipe set by Carl Christensen and Carl Mekel from four original bearing trees, condition in 1964 as follows; White pine 14 S75E 6 links, down, poor condition, pieces of face with scribe marks found; White Pine 24 N45E 47 links, down, Poor condition but upper face present; White Pine 24 S70W 38 links, a turned down stump with only axe marks visible; and White Pine 36 N62W 33 links, a rotted stump bottom.

SURVEYOR'S SEAL

Billy D. Buckler RLS 8887

Arthur O. Enger RIS 13581

Billy D. Buckler RLS 8887

All D. Buckler RLS 8887