

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44 N.R. 16 W


Schoolcraft COUNTY

DESCRIPTION OF CORNER Section Corner 10, 11, 14, 15

CORNER MONUMENT 2 1/2 brass cap set in reducing coupling attached to a 1 1/4" I.D. iron pipe. Cap stamped "10, 11, 14, 15, c.c."

DATE MONUMENT PLACED AND WITNESSED Monument set in 1949; rewritten 2/21/64.

WITNESSES TO CORNER..... Cedar 7 N47W 41 1/2 links, "S10, NBT"



do 6 N21E 32 " "S11, NBT"

do 10 S55E 44 " "S14, NBT"

AND

CIRCLE CORNER REGISTERED do 7 S9W 11 " "S15, NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner located and pipe set by Carl Christensen and Carl Makel from one original bearing tree, Cedar 12 S59W 10 links. BT still in position in 1964 although dead; has upper and lower faces with scribe marks legible.

SURVEYOR'S SEAL

SIGNED Arthur O. Enger RLS 13581 DATE 9/7/65
REGISTERED LAND SURVEYOR

Billy D. Buckler RLS 8887

4/13/72

Billy D. Buckler