

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44. NR. 16 W.

Schoolcraft

COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 7, 8, 17, 18

DESCRIPTION OF CORNER MONUMENT 2½" pipe with brass cap

WITNESSES TO CORNER 12" W. Birch N 26° E 40 links
" S 8 NBT "

11" Elm S 59° E 41 links
" S 17 NBT "

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-witnessed Corner as set by Carl Christianson, Manistique.
Cedar B.T. in place in good condition; bears S 83° W 3 links.
W. Pine B.T. in place in poor condition; bears N 53° E 36 links.

Corner lies 30 links East of River bank.

Evidence of use by several names on Cedar B.T.

Slater 9/15/38

T. Mellon

E. Anderson

R. Watson

P. Nelson

James Garvin

Carl Christianson

Corner is 2½ pipe with brass cap.

Corner re-witnessed 1-30-57.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 2-7-57