

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T ~~45-46~~ NR 17-W ..

Alger and Schoolcraft COUNTY

DESCRIPTION OF CORNER .. Section Corner common to Sections 4, -5, -32 and -33

DESCRIPTION OF CORNER MONUMENT 1" iron pipe with 4" brass cap ..

WITNESSES TO CORNER .. 7" Cedar .. S 78° E .. 54 links ..
Marked "S 4 NBT"

7" Cedar .. S 49° W .. 43 links ..
Marked "S 5 NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner from one Tam. B.T. in fair condition.

Corner found by Forestry Division Survey Crew while making a partial re-survey of this area.

Corner placed and witnessed January 4, 1957.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 1/7/57
REGISTERED LAND SURVEYOR