

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46 .. NR. 13 .. W

Schoolcraft .. COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 3 and 4

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 36" W. Pine Stump .. (1/4s NBT) .. N 19° E .. 30 Links

36" W. Pine Stump .. (1/4s NBT) .. N 31° W .. 41 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established on line between two Section Corners, and by single proportionate measure. No evidence of original corner. Corner lies 50 Links west of road.

Corner was placed and witnessed June 14, 1960.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 8/11/60
REGISTERED LAND SURVEYOR
Billy D. Buckler