

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T.46.. NR. 13.. W

S e b o p l e c r a f t . . . . . COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 16, 17, 20, 21 . .

DESCRIPTION OF CORNER MONUMENT Iron Pine in Monument Box . . . . .

WITNESSES TO CORNER . . . . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was recorded as set by Michigan State Highway Surveyors.

No evidence of original corner. Corner lies .06 1/2 chains west of E of M-77.

Location poster on west side of road.

Corner was placed and witnessed June 24, 1960 with Russell Hinds.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 8/11/60  
REGISTERED LAND SURVEYOR  
Billy D. Buckler