

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD ✓

T.46.. NR. 13.. W

Scheelecraft COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 4 and 9

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 10" Red Oak (1/4s NBT) N 25° E 82 Links

24" W. Pine Stump (1/4s NBT) S 75° E 119 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established midway and line between two Section corners. No evidence of original corner.

Corner was placed and witnessed June 24, 1960 with Russell Hinds.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR
Billy D. Buckler

DATE 8/11/60