

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46 N. R. 13W


Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 20-29

CORNER MONUMENT 1" Pipe with 4" Brass Cap.

DATE MONUMENT PLACED AND WITNESSED 8-15-61 with W. Miller, Aide

WITNESSES TO CORNER..... 8" Tamarack (1/4 S NBT) S62°E 27 1/2 links



6" Tamarack (1/4 S NBT) N33°W 61 1/2 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established midway and on line between two section corners.
No evidence of original corner.
Corner lies in thick alder marsh.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE December 28, 1961
REGISTERED LAND SURVEYOR
Billy D. Buckler