

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46 N R. 13W


Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/2 Corner between Sections 19-20

CORNER MONUMENT 1" Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 8-15-61 with Wm. Miller, Aide

WITNESSES TO CORNER..... 5" Tamarack (1/2 S NBT) N60°E 87 1/2 links



CIRCLE CORNER REGISTERED

No others near

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established midway and on line between two Section Corners.
No evidence of original corner.
Corner lies in open marsh.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE December 28, 1961
REGISTERED LAND SURVEYOR
Billy D. Buckler