

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 45-46N N.R. 13W


Schoolcraft COUNTY

DESCRIPTION OF CORNER East 1/16 Corner bet. Secs. 3-34

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9-16-70

WITNESSES TO CORNER..... 18" Y. Birch (E 1/16 BT) N72°W 6.6'



12" Soft Maple (E 1/16 BT) S14°W 9.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner lies 1.0' north of a 6" Hard Maple.

This corner placed midway and on line bet. Sec. Cor. to east and  $\frac{1}{4}$  Cor. to west.

SURVEYOR'S SEAL

SIGNED

*Billy D. Buckler*  
Billy D. Buckler

REGISTERED LAND SURVEYOR

DATE

10-15-70