

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46N N. R. 13W


Schoolcraft COUNTY

DESCRIPTION OF CORNER South 1/16 Cor. bet Secs. 33-34

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 9-16-70

WITNESSES TO CORNER..... 7" Cedar (S 1/16 BT) S60°E 20.8'



9" Cedar (S 1/16 BT) N43°W 12.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed midway and on line bet. Sec. Cor. to south and $\frac{1}{4}$ Cor. to north.
Corner lies in a thick, cedar swamp.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler

REGISTERED LAND SURVEYOR

DATE 10-15-70