

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 46N N.R. 13W


Schoolcraft COUNTY

DESCRIPTION OF CORNER North 1/16 Cor. bet. Secs. 33-34

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 7-16-70

WITNESSES TO CORNER..... 5" Jack Pine (N 1/16 BT) N85°E 16.3'



9" Jack Pine (N 1/16 BT) N33°W 10.9'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner lies on north edge of Hwy. M-28 clearing.

This corner placed midway and on line bet. Sec. Cor.  $\frac{1}{2}$  mile to north and  $\frac{1}{4}$  Cor. to south.

SURVEYOR'S SEAL

SIGNED

*Billy D. Buckler*  
Billy D. Buckler  
REGISTERED LAND SURVEYOR

DATE

10-15-70