

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46N N.R. 13W


Schoolcraft COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 27-28-33-34

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9-9-70

WITNESSES TO CORNER..... 11" Red Pine (S33 NBT) S32°W 101.7'



CIRCLE CORNER REGISTERED

11" Red Pine (S34 NBT) S57°E 87.8'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at site of an old scribed wood post.
Found points of two older posts in ground.
Found no evidence of the two original spruce witnesses.
Location checks well with other corners in the area.

Corner lies in an open marsh, north of the old Seney road.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 9-23-70