## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in SCHOOL CRAFT		Located In:	Corner Code ##	
1.	Public Land Survey	T 46N R 13W	_D-11	
		<u> </u>		
		T R T R		
2.	in Section	S R		
_		S † R S T R		
3		S T R		

Register of Deeds Stamp & File Number

4. Lot No. \_ ...... , Recorded Plat ...... 5. Private Claims . ... -

Gerald L. Wiggins, in a field survey on ... do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in times 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

. NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A Description of original monument and accessories and/or subsequent restoration:
- $D_{\approx}11-1/4$  Corner between sections 29 and 32. Found a 2" Pipe set by R.L.S. #21274.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- D-11 Set a D.N.R. monument in a found 2" pipe set by R.L.S. # 21274 and marked new witnesses.

- C Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- D-11 DNR Pipe inside of 2" pipe. All trees marked with Tags. 6" W. Pine, N79°E, 68.15' 8" Tamarack, N56°E, 30.70' 10" Aspen, N10°E, 14.70'

10" Aspen,

N42°W, 33.30' 10" Aspen,

Surveyor's Michigan License No.

