LAND CORNER RECORDATION CERTIFICATE

For corners in	Filing	Requirement of Act	74, Mich. P.A. 19)70		
Schoolcraft	Located In:	Corner Code #				
(County)	Located III.	Comer Code #				
1. Public Land Survey	T_46N_R_1 TR_ TR_	13W B3				
Property Controlling in Section Miscellaneous Property in Sec.	TR_ ST_46N_R_] STR_ STR_ STR_	[3N 1	-	Register of	Deeds Stamp	& File Number
4. Lot No, Recor	ded Plat			ARCD		
5. Private Claims	ivate Claims 1 Nov 06 2002				EFGH	
	B3 P	Nov 04 2002		2 6 5	4-3	2-1-1-
I, Stephan J. Szyszkoski requirements of P.A. 74, Michiga	, in a field survey on	, 19 do h	ereby state that under	4 - 7 - 8	910	-11-12
requirements of P.A. 74, Michiga conformance with regulations and United States Department of the that the corner points mentioned Board of Land Surveyors or by recovered, found as expressed be	rules therefore as required interior, Bureau of Land Mai in lines 3, 4 and 5 above we a Decree of a Court of	in the current manual of sun nagement or by a decree of a tere in conformance with the	vey instructions of the a Court of Law and /or	5 6 19 17 7 8 19 20	7 16 15	+
NOTE: Not more than 2 corr on this certificate.	ners, all in the same town	and range, may be record	led	9 10 30 29	28 27	26 25
				11		
				12 31 32	23334	3536
pinted out to me by F.C. Hall till in place, good condition 1-Sec. 7) West 1/16 corner i	n. 2 pipe with 2 bra	ass cap. 8° Tamarack S	860E 22 links, 6" W	.Pine S70W 29 li	inks.	originai 6.1.
B. Description of corner evid	dence found and/or met	hod applied in restoring o	or reestablishing corr	ner:		
33) Recovered the monument of a good condition, and at reco deg. different than the rec 7.372 chains and 39.947 chain no new accessories as describ 1-Sec. 7) Established the con rue bearing between monument	f record, a 2" iron pigord distance from the locord, the bearing to these respectively. Accorded below.	pe with a 2" brass cap, 1953 N8Ts, both in good he W.Pine checks. Dist epted the monument for portionate to the origi	probably placed by condition with over ances West and Eas the corner, made noticely the corner, made noticely the corner.	y Carl Christian ergrown blazes. t to adjacent se ew markings on t	The Tam was fection corners the 1953 NBTs,	found at S45E, were found and marked
C. Description of monument	for corner and accessor	ies established to pernet	uate locating the pos	sition of the corne	or.	
B3) Found 2" I.Pipe with 2" lazed, scribed, and set meas n: 2" Tamarack S45E 14.5' "1/49 2" W.Pine S71M 19.1' do " Spruce N70W 8.55' "1/48	brass cap. (1) : uring nails alum set : 5" * 7" B	Set 1"IDx36" I.pipe wit . MDNR cap. Blazed, so measuring nails in: .Spruce N37E 18.45' .Spruce S49E 4.6' .Spruce S08E 10.75'		STEPH SZYSZI LAN SURVI NG 33S		
"Spruce N26E 15.3' do et cedar post adjacent. Bear agnetic. Distances to nail denotes 1953 NBT. Signed by	rings are Bear:	Cedar S87W 8.35' ings are magnetic. Dis with tag. Rock	do stances are to Date	12/3/0	DS6 SURVEY STATES	***************************************
Surveyor's Michigan License I	Na ' 72	2001				·