

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T 46 .. NR 14 W ..

----- Schoolcraft ----- COUNTY

DESCRIPTION OF CORNER Section corner common to Sec.'s 19-20-29-30

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER

<u>20" Red Pine</u>	<u>S 25° W</u>	<u>64 links</u>
	<u>"S 30 NBT"</u>	
<u>7" Red Pine</u>	<u>S 38° E</u>	<u>72½ links</u>
	<u>"S 29 NBT"</u>	
<u>7" Jack Pine</u>	<u>N 47° W</u>	<u>44½ links</u>
	<u>"S 19 NBT"</u>	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced section corner from one yellow pine B.T. bearing N 52½° E 58 links.

B.T. is stub, burned but in fair condition.

Corner lies on sand ridge. No evidence of use.

Corner found by E. Hall, District Forester and R. Norkoli, Ass't.

Corner placed and witnessed January 17, 1958.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 1/17/58  
REGISTERED LAND SURVEYOR