

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46 NR. 14 W

Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 3 and 10

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 14" Red Pine (1/4" NBT) S 25° E 111 Links

15" Red Pine (1/4" NBT) N 83° W 107 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from two Yellow Pine Stumps (probable B.T.'s) bearing N 65° E 28 Links and S 43° W 31 Links. Found a discolored streak in soil at corner which could have been caused by a rotting wood stake. Found old blazes on Red Pine about 1 chain west of corner.

Corner was placed and witnessed April 21, 1960 with Frank J. Bray.
SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 5/18/60