

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. ~~46~~ 47 NR. . . 14 . . W

. . . Schoolcraft . . . COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 36 and 1

DESCRIPTION OF CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap

WITNESSES TO CORNER 18" Yellow Pine (1/4^s NBT) N 52° E 49 Links

18" W. Pine Stump (NBT) N 49° W 14 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from one W. Pine B.T., down and in poor condition. Faces and notch visible (18" W. Pine N 49° E, 22 Links.)

Corner was placed and witnessed July 7, 1960.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 8/11/60
REGISTERED LAND SURVEYOR
Billy D. Buckler