

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 46N N.R. 14W


Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 14-15

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 8-3-62

WITNESSES TO CORNER..... 9" Jack Pine ( $\frac{1}{2}$ S NBT) N52°W, 26 $\frac{1}{2}$  links



7" Jack Pine ( $\frac{1}{2}$ S NBT) N54°E, 13 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line between two section corners. No evidence of original corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE July 19, 1963  
REGISTERED LAND SURVEYOR  
Billy D. Buckler