MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 15-22

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITHESSED 8-3-62

WITHESSES TO CORNER. 15" Red Pine (\$\frac{1}{4}\$S NBT) \$S15^OE, 74 links

12" Tamarack, (\$\frac{1}{4}\$S NBT) \$S33^OW, 78 links

Corner lies 3/4 chains north of ditch

AND

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line between two section corners. No evidence of original corner.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

REGISTERED LAND SURVEYOR
Billy D. Buckler

DATE July 19, 1963