CONS. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 46N M.R. 14W

				Scl	noolcraft	COUNTY
DESCRIPTION OF CORNER _	1/4 corr	er between	sectio	ns 22-2	3	
CORNER MONUMENT	l" pipe	with 4" al	uminum	cap.		
DATE MONUMENT PLACED AND	WITHESSED	8-2-62	2			
WITHESSES TO CORNER	. 18"	red pine (ks NBT)	N18°W,	$68\frac{1}{2}$ links	
N 23	15"	Red pine (‡s NBT)	s60°W,	48½ links	
CIRCLE CORNER REGISTERED	AND	14-1				

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line between two section corners. No evidence or original corner.

SURVEYOR'S SEAL

Billy D. Buckler

Billy D. Buckler

Billy D. Buckler