Cons. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

Schoolcraft

DESCRIPTION OF CORNER 1/4 corner between Sections 20-21

CORNER MONUMENT 1" pipe with 4" aluminum cape

DATE MONUMENT PLACED AND WITHESSED 12-18-62

WITHESSES TO CORNER..... 16" Red Pine (\frac{1}{2}S NBT) N50^OE, 135 links

18" Red Pine Stub (\frac{1}{4}S NBT) S37^OW, 56\frac{1}{2} links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line between two section corners. No evidence of original corner.

SURVEYOR'S SEAL

NED _____

REGISTERED LAND SURVEYOR Billy D. Buckler

DATE _April 26, 1963