

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46 N.R. 14 W


Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 11-12

CORNER MONUMENT 1" Pipe with 1/4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 6-14-62

WITNESSES TO CORNER..... 12" W. Pine (1/4 S NBT) S 30° W 51 links



1 1/4" Red Pine (1/4 S NBT) N 70° W 76 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from one Tamarach Stump bearing S 34° E 50 links.
Stump in poor condition. Position of this stump checks with other corners in area.

No evidence of marks found on possible B.T.

Corner lies in West margin of swamp.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 4-2-64
REGISTERED LAND SURVEYOR
Billy D. Buckler