## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. <u>),6</u> #.R. <u>1), W</u>

	Schoolcraft		COUNTY	
DESCRIPTION OF CORNER 1/1; Corner between	en Sections 13 -	14		
CORNER HONUMENT	Aluminum Cap		•• ••	<del>.</del>
DATE MONUMENT PLACED AND WITNESSED	-62			
WITHESSES TO CORNER 7" Jack Pine	(1/4 S NBT)	s 51° w	18 links	
8# Jack Pine	(1/4 S NBT)	N 19° E	56 links	
AND CIRCLE CORNER REGISTERED				

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner re-established midway and on line between two Section Corners.

No evidence of original Corner.

SURVEYOR'S SEAL

SIGNED SILLY Suckles. DATE 11-2-611

RESISTENCE LAND SURVEYOR

Billy D. Buckler