

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 46 N. R. 14 W


Schoolcraft COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 4-5-8-9

CORNER MONUMENT 1" Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 11-5-62

WITNESSES TO CORNER..... 9" Hemlock (S 8 NBT) S 8° W 13½ links



9" Hemlock (S 9 NBT) S 27° E 13 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner lies 60 links West of Road.

This corner re-established on line between 1/4 Corner 1/2 mile North and a line tree 1½ miles South. Distance East to 1/4 Corner is good.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 4-2-64  
REGISTERED LAND SURVEYOR  
Billy D. Buckler