

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 46 N.R. 15W


Schoolcraft COUNTY

DESCRIPTION OF CORNER Section corner for sections  $\frac{19}{30}$ / $\frac{20}{29}$

CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap.

DATE MONUMENT PLACED AND WITNESSED 9-7-61

WITNESSES TO CORNER..... 5" Tamarack (S30 NBT) S73°W, 107 links



12" Norway Pine (S20 NBT) N81°E, 307 links

AND

CIRCLE CORNER REGISTERED

### DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established by single proportioned measurement (3 mile randoms and corrections were made in original survey).  
No original evidence.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE January 2, 1962  
REGISTERED LAND SURVEYOR  
Billy D. Buckler