

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 46 .. NR. 15 .. W

Schroeder .. COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 21, 22, 27, & 28.

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 6" Cedar (S 21 NBT) N 82° W 57 1/2 Links

8" Cedar (S 27 NBT) S 20° E 71 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from 12" cedar Stump N 40° W, 18 Links.

Other missing, old skid road in vicinity.

Corner was placed and witnessed July 19, 1960.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 7/28/60
REGISTERED LAND SURVEYOR
Billy D. Buckler