

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T.46.. NR. 15.. W

Scheelecraft COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 23, 24, 25, 26

DESCRIPTION OF CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap

WITNESSES TO CORNER 16" W, Pine Stump (S 24° NBT) N 24° E 54 Links

6" Spruce (S 25 NBT) S 18° E 46 Links

4" Spruce (S 26 NBT) S 37° W 37 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established by swamp edges 1/2 chain to south and west and 1/4 corners to south and north. Swamp to east checks fair.

Corner placed and witnessed August 24, 1960.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 9/15/60