## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T.46. NR 15 .. W

	_S_o_h_o_o_l_o_r a_f t COUNTY
DESCRIPTION OF CORNER 1/4	corner between Sections 23 and 24
DESCRIPTION OF CORNER MONL	MENT_l" Pipe with 4" Brass Cap
WITNESSES TO CORNER 8 W.	Pine _ (1/4s NBT) _ S 54° W _ 29_1/2 Links _
7" Red	Pine (1/4s_NBT) _ S 05° W _ 30 Links
22 <u>" W. 1</u>	Pine Stub (1/4s 23/24 NBT) _ S 75° E _ 20 Idnks

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from one W. Pine Stump bearing N 25° E, 35 Links and a Hemlock Stump S 25° W 20 Links. Found Notch on W. Pine. Several old blazes facing corner.

Corner was placed and witnessed August 23, 1960.

SURVEYORS SEAL

SIGNED SILL DATE 8/29/60 DATE 8/29/60 Billy D. Buckler